# Weathertzatton Assistance Program

# Work Order (Bid Form)

### **WORK ORDER INFORMATION**

*Work Order Name:* WO/15015SE-4154/1

Work Order Type: Weatherization

Audit Name: NA

**CLIENT INFORMATION** 

Client Name: Address:

Client ID: 15015SE-4154

Alt. Client ID: McMinn

**AGENCY INFORMATION** 

Agency: Southeast Tennessee Human Resource Agency Agency Phone: (423) 949-2191

**Address:** 312 Resource Rd. **Fax:** (423) 949-4023

Agency Contact: Gaskins, Glenn Work Phone:

Cell Phone: (865) 679-8303

Email Address: amerispechome20@bellsouth.net

Company Name & License Number:	
Contractor's Signature:	

### **COMMENT**

Site Built Home

Pre-1978. Lead Safe Weatherization Protocol Applies

## **Measures**

Measure 1 CO I	Monitor is Needed			Componen	ts			Inspected
	Attachment A- Standard ast Field Guide.	s for Wea	atheriza	ation Materia	als and			
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	CO monitor	Each	1					
	Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:		] ,	Sub Total:	
Field Notes:				-				

1		mproper Venting of Batl aust Fan Vent fan to ex			Componen	ts			Inspected
C		nts installed to outside of ent A- Standards for Wea			•				
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Bath Vent w/ Piping to Outside	Each	1					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Each	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Measure 3	Infiltration Redctn	Components	Inspected
ins 2. av re all	sulating. Seal HVAC Duct System. Total perage of about 8 per register. Higgister indicating a possible disconboots and joints prior to installing	ressure reading for registers was 77.4, an hest reading was 32.7 at left family room nect at this register. Mastic seal with fabric new duct insulation.	

Review plenum connection at air handler. Seal as needed.

				Estimated	1		Actuai	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Miscellaneous Su	Infiltration Reduction	Each	1					
Other Detail								
			Measur	e Sub Total:		] ;	Sub Total:	
Field Notes:								

	<i>Measure</i> 4 Furn	nace Tuneup			Componen	ts			Inspected
C	1056 pp	o Gas Central Furnace. Com. Contractor to convey orocedures to agency.							
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipme	Furnace Tuneup	Each	1					
		Includes labor cost. Must be completed by a licensed mechanical contractor. Must submit with invoice a completed tune up summary report.							
2	Labor	Furnace Tuneup	Each	1					
3	Other	Furnace Tuneup	Each	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

tor to remove damaged/d llow specifications of Sou		ed duct					
now specifications of oou	theast W				ce with		
			Estimated	1		Actual	
Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Duct Insulation	SqFt	377					
Includes labor cost. Contractor must use a minimum of R-6 insulation. All foil tape should be free of bubbles. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
Duct Insulation	SqFt	377					
		Measur	e Sub Total:			Sub Total:	
	Duct Insulation Includes labor cost. Contractor must use a minimum of R-6 insulation. All foil tape should be free of bubbles. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.	Duct Insulation SqFt  Includes labor cost. Contractor must use a minimum of R-6 insulation. All foil tape should be free of bubbles. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.  Duct Insulation SqFt	Duct Insulation SqFt 377  Includes labor cost. Contractor must use a minimum of R-6 insulation. All foil tape should be free of bubbles. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.  Duct Insulation SqFt 377	Description / Comment  Duct Insulation  Includes labor cost. Contractor must use a minimum of R-6 insulation. All foil tape should be free of bubbles. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.  Duct Insulation  SqFt  377  Unit Cost  SqFt  377	Duct Insulation SqFt 377  Includes labor cost. Contractor must use a minimum of R-6 insulation. All foil tape should be free of bubbles. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.  Duct Insulation SqFt 377	Description / Comment Units Qty Unit Cost Total Qty  Duct Insulation Includes labor cost. Contractor must use a minimum of R-6 insulation. All foil tape should be free of bubbles. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.  Duct Insulation  SqFt 377	Description / Comment     Units     Qty     Unit Cost     Total     Qty     Unit Cost       Duct Insulation     SqFt     377     Includes labor cost.       Contractor must use a minimum of R-6 insulation. All foil tape should be free of bubbles. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.     SqFt     377       Duct Insulation     SqFt     377     Includes labor cost.

	Measure 6 DWI comment	H Pipe Insulation			Componen	ts			Inspected
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
		Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	DHW Pipe Insulation	Each	1					
3	Other	DHW Pipe Insulation	Each	1					
(	Other Detail								
							<u> </u>		
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

1	<i>Measure</i> 7 DWH	l Tank Insulation			Componer	nts			Inspected
C	omment								
					Estimate	d		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equip	DHW Tank Insulation	Each	1					
		Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	DHW Tank Insulation	Each	1					
3	Other	DHW Tank Insulation	Each	1					
C	Other Detail						_		
_				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

walls w					<i>ts</i> E,N,S	, • •		
specific	states that walls are not ins rith dense pack cellulose a cations of Southeast Weat	it a rate o	f 3.5# d	cu. Ft. Adhe	•	ulate		
Contrac beginni	ctor to consult with client cing.	concerning	g insula	ating proced	ures pric	or to		
				Estimated	1		Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	1168					
Other Detail	7					<b>-</b>	T	
	]					]		
			Measure	Sub Total:		]	Sub Total:	
Field Notes:								
Measure 9 Floo	or Ins. R-19 R19 batts at crawlspace jo	ist systen		-	c. 2092 s			Inspected
Measure 9 Floo		ist systen		•	c. 2092 s		space  Actual	Inspected
Measure 9 Floo		ist systen		joists, 24"o	c. 2092 s			Inspected
Measure 9 Floo	R19 batts at crawlspace jo	·	n. 2x10	joists, 24"0	c. 2092 s	sq ft	Actual	
Measure 9 Floo Comment Install F Material / Labor Insulation	R19 batts at crawlspace jo  **Description / Comment**  Floor Insulation -	Units	2x10 <i>Qty</i>	joists, 24"0	c. 2092 s	sq ft	Actual	
Measure 9 Floo Comment Install F Material / Labor Insulation	R19 batts at crawlspace jo  **Description / Comment**  Floor Insulation -	Units	2x10 <i>Qty</i>	joists, 24"0	c. 2092 s	sq ft	Actual	
Measure 9 Floo	R19 batts at crawlspace jo  **Description / Comment**  Floor Insulation -	Units SqFt	Qty 2092	joists, 24"0	c. 2092 s	Qty	Actual	Inspected

Measure 10 Rep	ace A/C			Componen	ts AC			Inspected
	tor to follow Manual J re y in place.	commenda	ations 1	or sizing, A	2.5 ton ι	ınit is		
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Cooling Equipmen	Central A/C -	Each	1					
2 Labor	Central A/C -	Each	1					
Other Detail								
			Measur	e Sub Total:		]	Sub Total:	
(Wal Comment Home is follow re Painting	pre-1978. Follow lead sequirements of EPA Lea . Contractor to adhere to	safe weath d -Based F o 4 step re	erizatio Paint R quirem	enovation, ents of WA	Contract Repair ar P ARRA	ıd		Inspected
for deter	rmining need for presen	ce of Gertii	riea Re	ennovator/Fi <b>Estimate</b> d			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Equipment	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measure	e Sub Total:			Sub Total:	

Client Name: Client ID: 15015SE-4154 Alt. Client ID: McMinn Work Order (Bid Form)
Work Order Name: WO/15015SE-4154/1
Report Run On: 4/29/2010

DOE Weatherization Assistant Version 8.6.0 Page 10 of 10